

# 2018 DOOSAN DL420-5

UNIT: DWGCWLBJEJ1010639

Current Location: R.B. EVERETT & CO., Haltom City, TX 76117, 817-299-0010



## UNIT SPECS

Customer PNC Equipment Finance

## RECONDITIONING

Quick Coupler To Arms Pins: Heavy movement	\$4,000	Articulating Center Pins Rubber steer bump stops worn out	\$650
Frame Condition: Front frame top cover over hydraulic valve missing	\$750	Replace All 4 Tires	\$32,000
Glass: Windshield cracked	\$1,500	Steering Controls: Column heavy movement Lock to tilt doesn't lock every time	\$400
Hydraulic Controls: Loose	\$400	DEF / AdBlue Tank: Housing damaged/Twisted	\$2,500
Paint: Damage	\$2,500	Body Panels: Left battery box damaged, Right battery box damaged,	\$4,000
Right cab steps missing, Rt rear Step damaged	\$1,200	Exterior Lights: 6 Inoperable / damaged / missing	\$1,800
Cab/Canopy Overhead Structural Framework: Bent metal Guards	\$1,750	Hoses (Hydraulics): Coupler lines mount to loader arm damage Rt loader arm cylinder hoses steel cords showing	\$1,500
Bucket Tilt Cylinder: Barrel damaged Wiper seal damaged Grease fitting rod end damaged	\$5,500	Loader Bucket Condition: Mounts loose to coupler, Worn	\$750
Loader Bucket Cutting Edge: Edge worn Not turntable missing center edge retaining bolts	\$650	Forks: Quick couple top mounts heavy wear	\$400
Grille damaged	\$2,500	Hood damaged	\$4,000
Front lower head light Arm Guards Damaged	\$350	Radiator access doors' latches broken	\$600
Belly pans Damaged	\$1,500	Counter Weight Bolts Broken Both Sides	\$400
Def Codes/Warnings	\$3,500		

**Total**

**\$75,100**



































PASADENA, TEXAS (281) 991-8161  
HALTOM CITY, TEXAS (817) 299-0010



















































































































































